

## PIC18(L)F1XK50 Silicon Errata and Data Sheet Clarification

The PIC18(L)F1XK50 family devices that you have received conform functionally to the current Device Data Sheet (DS41350E), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).


The errata described in this document will be addressed in future revisions of the PIC18(L)F1XK50 silicon.

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (**B0**).

Data Sheet clarifications and corrections start on [page 7](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate web site ([www.microchip.com](http://www.microchip.com)).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. Based on the version of MPLAB IDE you are using, do one of the following:
  - a) For MPLAB IDE 8, select *Programmer > Reconnect*.
  - b) For MPLAB X IDE, select *Window > Dashboard* and click the **Refresh Debug Tool Status** icon (  ).
5. Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

**Note:** If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC18(L)F1XK50 silicon revisions are shown in [Table 1](#).

**TABLE 1: SILICON DEVREV VALUES**

Part Number	Device ID <sup>(1)</sup>	Silicon Revision ID <sup>(2)</sup>			
		A6	A7	A8	B0
PIC18LF13K50	4700h	06h	07h	08h	00h
PIC18LF14K50	4720h	06h	07h	08h	00h
PIC18F13K50	4740h	06h	07h	08h	00h
PIC18F14K50	4760h	06h	07h	08h	00h

- Note 1:** The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of configuration memory space. They are shown in hexadecimal in the format "DEVID DEVREV".
- 2:** Refer to the "*PIC18(L)F1XK50 Flash Memory Programming Specification*" (DS41342) for detailed information on Device and Revision IDs for your specific device.

# PIC18(L)F1XK50

**TABLE 2: SILICON ISSUE SUMMARY**

Module	Feature	Item Number	Issue Summary	Affected Revisions <sup>(1)</sup>			
				A6	A7	A8	B0
ADC (Analog-to-Digital Converter)	Conversions	1.1	INL error and acquisition time.	X	X		
ADC (Analog-to-Digital Converter)	Conversions	1.2	May fail in RUN mode.	X			
ADC (Analog-to-Digital Converter)	Conversions	1.3	High pin leakage.	X	X	X	
ADC (Analog-to-Digital Converter)	Conversions	1.4	Offset error.	X	X		
ADC (Analog-to-Digital Converter)	Conversions	1.5	ADC conversion does not complete.	X	X		
MSSP (Master Synchronous Serial Port)	Transmit Setup	2.1	SPI and I <sup>2</sup> C™ clock and bit issues.	X	X	X	X
MSSP (Master Synchronous Serial Port)	Receive mode	2.2	SSPIF flag set early.	X	X	X	X
System Clocks	HFINTOSC	3.1	Frequency instability.	X	X		
System Clocks	HFINTOSC	3.2	Frequency shift on Reset.	X			
EUSART	Receive mode	4.1	RCIDL bit issue.	X			
EUSART	OERR flag	4.2	Cannot clear the OERR flag.	X	X		
EUSART	Asynchronous mode	4.3	TX/CK improperly driven.	X	X	X	X
CPU	Sleep	5.1	Reset on Wake-up.	X	X		
Timer1 Oscillator	Operations	6.1	Fails to operate above 90°C.	X	X	X	
IOC (Interrupt-on-Change)	Multiple Sources	7.1	Invalid interrupts.	X	X	X	X
Boot Block Memory	Code Protection	8.1	BBSIZ selection is invalid for code-protect.	X	X	X	X
Enhanced/Capture/Compare PWM (ECCP)	Special Event Trigger	9.1	Will not start A/D conversion.	X	X		

**Note 1:** Only those issues indicated in the last column apply to the current silicon revision.

## Silicon Errata Issues

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (**B0**).

### 1. Module: ADC (Analog-to-Digital Converter)

- 1.1 Offset error is 3 LSB typical, 7 LSB maximum, including an acquisition time dependent component (~2 LSB).

#### Work around

The time dependent error is insignificant when the time between conversions is less than 100 ms. When the time since the previous conversion is greater than 100 ms, take two ADC conversions and discard the first.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X						

- 1.2 When the ADC is configured to operate with the internal FRC oscillator (ADCON2<2:0> = X11) and the device is not in Sleep, then the ADC may fail to complete the conversion which is indicated by the GO/DONE bit of the ADCON0 register remaining in the GO state indefinitely. This condition can be cleared by a device Reset or by clearing the ADON bit of the ADCON0 register.

#### Work around

- Select a clock source that is not FRC.
- Set the ADIE bit of the PIE1 register and clear the ADIF bit of the PIR1 register, then put the part to Sleep immediately after setting the GO/DONE bit of the ADCON0 register. The device will perform the conversion during Sleep and Wake at the completion.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X							

- 1.3 ADC conversion on AN3/OSC2 will have large INL error up to approximately 8 LSB.

#### Work around

None for the AN3 pin. For better accuracy, use another analog pin.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X	X					

- 1.4 The offset error incorrectly exceeds the data sheet specifications if time between conversions is longer than 10 ms. If the time between conversions is greater than 10 ms, the offset error is 1 LSB typical and 3.3 LSB maximum.

#### Work around

The time dependent error is insignificant when the time between conversions is less than 10 ms. When the time between conversions is greater than 10 ms, take two back-to-back ADC conversions and discard the results of the first conversion.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X						

- 1.5 Under certain device operating conditions, the ADC conversion may not complete properly. When this occurs, the ADC Interrupt Flag (ADIF) does not get set, the ADGO/DONE bit does not get cleared, and the conversion result does not get loaded into the ADRESH and ADRESL result registers.

#### Work around

Select the dedicated RC oscillator as the ADC conversion clock source and perform all conversions with the device in Sleep.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X						

# PIC18(L)F1XK50

## 2. Module: MSSP (Master Synchronous Serial Port)

### 2.1 Short First Clock Pulse During SPI

When the SPI clock is configured for Timer2/2 (SSPCON1<3:0> = 0011), the first SPI high time may be short.

#### Work around

Option 1: Ensure TMR2 value rolls over to zero immediately before writing to SSPBUF.

Option 2: Turn Timer2 off and clear TMR2 before writing SSPBUF. Enable TMR2 after SSPBUF is written.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X	X	X				

### 2.2 SSPIF is Set Prematurely During SPI

The MSSP interrupt flag bit is set at one-half clock cycle before it should be, if modes 1 or 3 are used. This affect can be seen in the following situations:

1. Mode 1: CKP = 0, CKE = 0
2. Mode 3: CKP = 1, CKE = 0

It is most notable if the SPI clock is used at low-clock speeds. If the user responds to the interrupt and writes to SSPBUF before the intended interrupt time, then the WCOL (Write Collision) bit will be set and the transmission will not occur. Future transmissions will not occur until the WCOL bit is cleared.

#### Work around

Delay at least one-half period length of time before writing to SSPBUF after the SSPIF is set, if using modes 1 or 3.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X	X	X				

## 3. Module: System Clocks

### 3.1 Frequency Instability

HFINTOSC output frequency may have up to 1% short term frequency instability.

#### Work around

Use the HS, XT or EC clock modes.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X						

### 3.2 Frequency Shift on Reset

The internal oscillator module may experience a  $\pm 1\%$  frequency shift after a Reset. The frequency shift is not consistent and could cause the oscillator to operate outside of the 2% specification.

#### Work around

To minimize the chances of experiencing the frequency shift, the following steps should be taken:

1. Operate the internal oscillator at 8 MHz or 2 MHz.
2. Use an external pull-up on  $\overline{\text{MCLR}}$  or use internal MCLR mode.
3. Disable the Power Reset Timer (PWRT).
4. The bypass capacitor and Voltage Regulator Capacitor (VCAP) should be used appropriately to minimize noise in the device.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X							

## 4. Module: EUSART

### 4.1 RCIDL Bit

In Asynchronous Receive mode, the RCIDL bit of the BAUDCON register will properly go low when the RX input goes low at the leading edge of a Start bit. If the RX input stays low for less than 1/8<sup>th</sup> of a bit time, then the Start bit is invalid and the RCIDL should go high. However, the RCIDL bit will stay low improperly until a valid Start bit is received.

#### Work around

When monitoring the RCIDL bit, measure the length of time between the RCIDL going low and the RCIF flag going high. If this time is greater than one character time, then restore the RCIDL bit by resetting the EUSART module. The EUSART module is reset when the SPEN bit of the RCSTA register is cleared.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X							

### 4.2 OERR Bit

The OERR flag of the RCSTA register is reset only by clearing the CREN bit of the RCSTA register or by a device Reset. Clearing the SPEN bit of the RCSTA register does not clear the OERR flag.

#### Work around

Clear the OERR flag by clearing the CREN bit instead of clearing the SPEN bit.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X						

### 4.3 Asynchronous Mode

In Asynchronous mode when TXEN = 0, the TX/CK output is improperly driven. All mid-range parts tri-state the TX/CK pin when TXEN = 0 in Asynchronous mode.

#### Work around

None.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X	X	X				

## 5. Module: CPU

### 5.1 Reset on Wake-up

If a wake from Sleep event occurs during the execution of a Sleep command, the device may reset. This Reset will be seen as a Power-on Reset to the device.

#### Work around

1. Disable all asynchronous interrupt before going to Sleep.
2. Make sure the timing of an asynchronous interrupt will not happen during the execution of the SLEEP instruction.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X						

## 6. Module: Timer1 Oscillator

### 6.1 Operation above 90°C

The Timer1 oscillator does not operate above 90°C.

#### Work around

None.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X	X					

## 7. Module: IOC (Interrupt-on-Change)

### 7.1 IOC (Interrupt-on-Change) False Wake-up

When IOC is enabled for multiple pins to wake-up the processor from Sleep, invalid interrupts or wake-ups may occur.

#### Work around

Use only one pin as IOC with Sleep.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X	X	X				

# PIC18(L)F1XK50

---

## 8. Module: Boot Block Memory

### 8.1 BBSIZ Selection is Invalid for Code-Protect

When code-protecting the Boot Block with the CPB bit in CONFIG5H, the smaller Boot Block size is used, regardless of the BBSIZ bit selection in CONFIG4L. If Block 0 is also code-protected, the full range of memory from the Boot Block through Block 0 is protected; no intermediate program memory is left unprotected.

#### Work around

None.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X	X	X				

## 9. Module: Enhanced/Capture/Compare PWM (ECCP)

### 9.1 Will not Start A/D Conversion

When the ECCP is configured to work in Compare mode as a Special Event Trigger (CCP1M<3:0> = 1011), the special event trigger will not set the GO/DONE bit of the ADCON0 register and A/D conversion will not take place.

#### Work around

In the interrupt set ADCON0bits.GO = 1 with software after the CCPIF is set.

#### Affected Silicon Revisions

A6	A7	A8	B0				
X	X						

## Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS41350E):

<p><b>Note:</b> Corrections are shown in <b>bold</b>. Where possible, the original bold text formatting has been removed for clarity.</p>
---

None.

# PIC18(L)F1XK50

---

## APPENDIX A: DOCUMENT REVISION HISTORY

### **Rev A Document (10/2008)**

Initial release of this document

### **Rev B Document (8/2009)**

Updated Errata to new format; minor edits.

Data Sheet Clarifications:

Added Modules 1-8 to add QFN package information to data sheet.

### **Rev C Document (05/2010)**

Removed 'Rev. A6' from the title; Added A7 and A8 silicon revisions to Table 1 and Table 2; Removed Note 2 from Table 1; Updated Module 1.4; Added Module 1.5; Removed Table 3; Removed Modules 2.2, 2.3, 2.4, 2.5, 2.6; Added Modules 3.1 and 3.2; Updated Module 4; Added Modules 5.1, 5.2, 5.3, 6 and 7; Updated the Affected Silicon Revision section adding A7 and A8.

Data Sheet Clarifications:

Removed Modules 1 to 8. Data Sheet updated.

### **Rev D Document (07/2011)**

Added Silicon revision B0; Deleted Module 4, Timer1 and renumbered Modules.

### **Rev E Document (11/2011)**

Updated Errata to new format; Added Module 2.2.

### **Rev F Document (02/2012)**

Added Module 7, Interrupt-on-Change.

### **Rev G Document (07/2012)**

Added MPLAB X IDE; Added Module 8, Boot Block Memory.

### **Rev H Document (11/2012)**

Added Module 9, Enhanced Capture/Compare/PWM (ECCP).



---

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

#### **Trademarks**

The Microchip name and logo, the Microchip logo, dsPIC, FlashFlex, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, PIC<sup>32</sup> logo, rPIC, SST, SST Logo, SuperFlash and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Hampshire, HI-TECH C, Linear Active Thermistor, MTP, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

Analog-for-the-Digital Age, Application Maestro, BodyCom, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, HI-TIDE, In-Circuit Serial Programming, ICSP, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, mTouch, Omniclient Code Generation, PICC, PICC-18, PICDEM, PICDEM.net, PICkit, PICtail, REAL ICE, rFLAB, Select Mode, SQI, Serial Quad I/O, Total Endurance, TSHARC, UniWinDriver, WiperLock, ZENA and Z-Scale are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

GestIC and ULPP are registered trademarks of Microchip Technology Germany II GmbH & Co. & KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2008-2012, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

ISBN: 9781620766576

**QUALITY MANAGEMENT SYSTEM**  
**CERTIFIED BY DNV**  
**== ISO/TS 16949 ==**

*Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC<sup>®</sup> MCUs and dsPIC<sup>®</sup> DSCs, KEELOQ<sup>®</sup> code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*



# MICROCHIP

## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Cleveland**  
Independence, OH  
Tel: 216-447-0464  
Fax: 216-447-0643

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Farmington Hills, MI  
Tel: 248-538-2250  
Fax: 248-538-2260

**Indianapolis**  
Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

**Santa Clara**  
Santa Clara, CA  
Tel: 408-961-6444  
Fax: 408-961-6445

**Toronto**  
Mississauga, Ontario,  
Canada  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

**Asia Pacific Office**  
Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Harbour City, Kowloon  
Hong Kong  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**Australia - Sydney**  
Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

**China - Beijing**  
Tel: 86-10-8569-7000  
Fax: 86-10-8528-2104

**China - Chengdu**  
Tel: 86-28-8665-5511  
Fax: 86-28-8665-7889

**China - Chongqing**  
Tel: 86-23-8980-9588  
Fax: 86-23-8980-9500

**China - Hangzhou**  
Tel: 86-571-2819-3187  
Fax: 86-571-2819-3189

**China - Hong Kong SAR**  
Tel: 852-2401-1200  
Fax: 852-2401-3431

**China - Nanjing**  
Tel: 86-25-8473-2460  
Fax: 86-25-8473-2470

**China - Qingdao**  
Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

**China - Shanghai**  
Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

**China - Shenyang**  
Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

**China - Shenzhen**  
Tel: 86-755-8203-2660  
Fax: 86-755-8203-1760

**China - Wuhan**  
Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

**China - Xian**  
Tel: 86-29-8833-7252  
Fax: 86-29-8833-7256

**China - Xiamen**  
Tel: 86-592-2388138  
Fax: 86-592-2388130

**China - Zhuhai**  
Tel: 86-756-3210040  
Fax: 86-756-3210049

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444  
Fax: 91-80-3090-4123

**India - New Delhi**  
Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

**India - Pune**  
Tel: 91-20-2566-1512  
Fax: 91-20-2566-1513

**Japan - Osaka**  
Tel: 81-66-152-7160  
Fax: 81-66-152-9310

**Japan - Yokohama**  
Tel: 81-45-471-6166  
Fax: 81-45-471-6122

**Korea - Daegu**  
Tel: 82-53-744-4301  
Fax: 82-53-744-4302

**Korea - Seoul**  
Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

**Malaysia - Kuala Lumpur**  
Tel: 60-3-6201-9857  
Fax: 60-3-6201-9859

**Malaysia - Penang**  
Tel: 60-4-227-8870  
Fax: 60-4-227-4068

**Philippines - Manila**  
Tel: 63-2-634-9065  
Fax: 63-2-634-9069

**Singapore**  
Tel: 65-6334-8870  
Fax: 65-6334-8850

**Taiwan - Hsin Chu**  
Tel: 886-3-5778-366  
Fax: 886-3-5770-955

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7828  
Fax: 886-7-330-9305

**Taiwan - Taipei**  
Tel: 886-2-2508-8600  
Fax: 886-2-2508-0102

**Thailand - Bangkok**  
Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**UK - Wokingham**  
Tel: 44-118-921-5869  
Fax: 44-118-921-5820

10/26/12