

Date: 07/11/2017 PCN:483

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following products. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Hardware and software

Products Affected

Part Number	Description	Old Revision	New Revision
SLC80081201S	SLC 8000 8-Port Advanced Console Manager, Single AC Power Supply	C13	D14
SLC80082201S	SLC 8000 8-Port Advanced Console Manager, Dual AC Power Supply	C13	D14
SLC80161201S	SLC 8000 16-Port Advanced Console Manager, Single AC Power Supply	C13	D14
SLC80162201S	SLC 8000 16-Port Advanced Console Manager, Dual AC Power Supply	C13	D14
SLC80162401S	SLC 8000 16-Port Advanced Console Manager, Dual DC Power Supply	C12	D13
SLC80321201S	SLC 8000 32-Port Advanced Console Manager, Single AC Power Supply	C13	D14
SLC80322201S	SLC 8000 32-Port Advanced Console Manager, Dual AC Power Supply	C13	D14
SLC80322401S	SLC 8000 32-Port Advanced Console Manager, Dual DC Power Supply	C12	D13
SLC80481201S	SLC 8000 48-Port Advanced Console Manager, Single AC Power Supply	C13	D14
SLC80482201S	SLC 8000 48-Port Advanced Console Manager, Dual AC Power Supply	C13	D14
SLC80482401S	SLC 8000 48-Port Advanced Console Manager, Dual DC Power Supply	C12	D13
SLC81161201S	SLC 8000 Advanced Console Manager, USB 16-Port, Single AC Power Supply, RoHS	B11	C12
SLC81162201S	SLC 8000 Advanced Console Manager, USB 16-Port, Dual AC Power Supply, RoHS	A11	B12
SLC82321201S	SLC 8000 Advanced Console Manager, RJ45 16-Port, USB 16-Port, Single AC Power Supply, RoHS	B12	C13

Description and Extent of Change

Hardware Changes:

These products now bear the China Compulsory Certificate (CCC) mark. This is a compulsory safety mark allowing for these products to be imported and sold in China. This hardware change does not include a fit, form or function related change.

Software Changes:

Lantronix is pleased to announce the release of new and improved firmware version 7.4.0.0. The release includes new features and bug fixes including:

- Enhance security features including support for Diffie Hellman-14 (DH-14) and Secure Hash Algorthms-256 (SHA256)
- SNMP v3 traps (non-FIPS mode)
- Built-in support for Sensorsoft environmental sensors
- HTML5 support for Java-free web based Telnet/SSH remote access to console ports that is browser independent

7535 Irvine Center Drive | Suite 100

Irvine, CA 92618 USA



Support for Siemens USB drivers with programmable VID/PID

For customers that would like to take advantage of the new capabilities of firmware version 7.4.0.0, the new firmware available for download from our website: http://www.lantronix.com/support/downloads.

Reason for Change

New firmware provides enhanced security feature, support for environmental monitoring sensors and bug fixes..

Effect of Change on Fit, Form, or Function

The 7.4.0.0 release adds enhanced security features and bug fixes. Please consult software release notes for full description of new features, enhancements and bug fixes. The hardware change affects labeling requirements only. No functional hardware was updated in order to achieve CCC certification.

Effective Date of Change

Affected products with firmware version 7.4.0.0 will begin shipping from the factory by July 14st 2017 If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.