

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M001046

DATE: 29-Nov-2021

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1845E-100+	N/A	31-May-2022	27-Nov-2022	Part can no longer be manufactured
Discontinuance	MAX203CWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX203CWP+TG36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX203ECWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX203EEWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX203EEWP+TG36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX203EWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX203EWP+TG36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX233ACWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX3233ECWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX3233ECWP+TG36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX3235ECWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX3235ECWP+TG36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX3235EEWP+G36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured
Discontinuance	MAX3235EEWP+TG36	N/A	29-Nov-2022	28-May-2023	Part can no longer be manufactured