

Date: 01/02/2019 PCN: 566

# PRODUCT CHANGE NOTICE

## Dear Lantronix Customer,

The purpose of this communication is to inform you of the immediate availability of new software release for XPort Pro.

## **Change Type**

Software

## **Products Affected**

#### XPort Pro (Evolution)

| Part Number      | Description   | Old<br>Revision | New<br>Revision |
|------------------|---|-----------------|-----------------|
| XPP1002000-02R   | XPort Pro Device Networking Module, Evolution OS, AES Encryption, 16MB SRAM, Extended Temperature, RoHS, Bulk   | E15             | F15             |
| XPP100200S-02R   | XPort Pro Device Networking Module, Evolution OS, AES Encryption, 16MB SRAM, Extended Temperature, RoHS, Sample | E16             | F16             |
| XPPDK1000-EVO-02 | XPort Pro Evolution Development Kit with 16 MB RAM, RoHS  | D14             | E14             |

## **Description and Extent of Change**

Lantronix is pleased to announce the release of new and improved **XPort Pro Evolution OS firmware version 5.5.0.2R5**. It provides security protocol enhancement along with a bug fix.

Key highlights of this release are:

- Enhancement to TLS 1.2 protocol- Elliptic curve with SHA-2 HASH
- DHCP Bug fix after ARP timeout

## Effect of Change on Fit, Form, Function, Quality, or Reliability

| Product Variant       | Part Number  | Software Version            |
|-----------------------|--|-----------------------------|
| XPort Pro (Evolution) | XPP1002000-02R<br>XPP100200S-02R<br>XPPDK1000-EVO-02 | Firmware Version: 5.5.0.2R5 |

The updated SDK release is available for download via Lantronix forums (http://forums.lantronix.com).

## **Effective Date of Change**

Affected products will begin shipping with the new software from the factory starting 1st February 2019.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.

7535 Irvine Center Drive | Suite 100 Irvine, CA 92618 USA

