

# Product Change Notice

QD4-099 Rev.A1

Product(s) Affected: ACP-1106HTT-1013 Series / ACP-1076HTT-1013 Series

Effective date: July 22, 2022

Last time buy date: November 30, 2022

Product Change Description:

Due to the motherboard (GENE-APL5) material shortage/long lead time on ACP-1076/1106 series, we decided to adopt the same spec to replace the original one. This replacement material passes the functions test without affecting system performance or drivers change.

For the new part number, please refer to below come to the parison table, please be kindly noted and then, keeps for your attention and understanding. (註: 不得提及有關日期的字眼, 避免造成混淆)

Benefits:  Impacts:

To avoid material shortage and keep product production.

Details of Affected Products:

Pre-Change	Post-Change
ACP-1106HTT-A1-1013	ACP-1106HTT-A1-1014
ACP-1106HTT-A3-1013	ACP-1106HTT-A3-1014
ACP-1106HTT-B1-1013	ACP-1106HTT-B1-1014
ACP-1106HTT-B3-1013	ACP-1106HTT-B3-1014
ACP-1076HTT-A1-1013	ACP-1076HTT-A1-1014
ACP-1076HTT-A3-1013	ACP-1076HTT-A3-1014
ACP-1076HTT-B1-1013	ACP-1076HTT-B1-1014
ACP-1076HTT-B3-1013	ACP-1076HTT-B3-1014

Note: Include all standard part numbers, R part numbers, and C part numbers.

Yours sincerely,

Peter Yang 2022.07.22 (註: 必須SBU head 簽名)

RMD (例: Network Security Division)