

## **Product Change Notification**

PCN No.	Quectel_PCN_2021012902	Date of Issue (DD/MM/YYYY)	29/01/2021	
1. General Information				
Type of Change	Key Component Change			
	For MC60 module:			
Description of	Due to the severe shortage of PA (model: <b>RF7198</b> ), the PA needs to be replaced with PA			
Change	(model: HS8298H) to ensure stable supply. The ordering code for new PA (model:			
	HS8298H) has been changed to MC60CB-04-STD.			
Reason of	Due to the severe shortage of current PA, the current PA needs to be replaced to ensure			
Change	stable supply.			

## 2. Information of Affected Products and Alternative Products

Affected Products Information		Alternative Products Information	
Model	Ordering Code	Model	Ordering Code
MC60	MC60CA-04-BLE	MC60	MC60CB-04-STD

#### **Sample Release Date:**

Samples of Alternative Products will be available from 23/02/2021 (DD/MM/YYYY)

#### **Shipment Date:**

Shipment of Alternative Products will start from 23/03/2021 (DD/MM/YYYY) if no statement is received.

# 3. Impacts of the Change

Risk Assessment	<ol> <li>The ordering code (OC) will be changed.</li> <li>It will not affect any function and electrical performance of MC60 module, and there is no other risk.</li> </ol>	
Suggested	After rigorous and complete tests and reviews, Quectel confirms that the Alternative	
Implementation	Products provide the same performance and function as before. You can feel secure to	
Plan	use them.	

### 4. Customer Acknowledgement of Receipt

Please acknowledge receipt of this change notification by replying to info\_PCN@quectel.com
If no feedback is received before the Shipment Date, then Quectel may deem that this change has been tacitly accepted and can implement the change as indicated above.