



Product information



Code No. : T0051516899

Safety Rests with Stop+Go function for FE Irons with WFE or WFE P Basic unit pneumatic (for WFE) safety rest with Stop+Go function with fibre optic sensor for WSP 80FE

This safety rest is ESD safe.

Safety rests with Stop+Go function with fibre optic sensor for soldering irons WSP 80, WP80, WP 120

The Weller safety rests with Stop+Go function are recommended acessories for FE irons using the WFE or WFE P extraction units. A fibre optic sensor switches the extraction unit on when the FE iron is removed from the safety rest and when the FE iron is replaced in the safety rest, after a short delay to gather the fumes from any solder on the tip it switches the unit off. This reduces running costs.