

Product Change Notice

QD4-099 Rev.A1

Product(s) Affected: MIX-H310D1 series

Effective date: December 22, 2022

Last time buy date: June 30, 2023

Product Change Description:

Due to TPM chip NPCT650 had EOL and no replace part. We recommend change to firmware TPM. Therefore, needing change BIOS for firmware TPM function. We adapt the new solution to replace the EOL components on motherboard to keep product's stability and reliability without any product function change. For the new part number, please refer to below comparison table, please be kindly noted and thanks for your attention and understanding.

Benefits: ☐ Impacts: ☒

To avoid material EOL issue and keep product production on the same PCB.

Details of Affected Products:

Pre-Change	Post-Change
MIX-H310D1-A10-HH	MIX-H310D1-A13-HH-FTPM
MIX-H310D1-A10-A-0232-JFS	TBD
MIX-H310D1-A10-HD-T20-ONYX	TBD
MIX-H310D1-A10-HD-T20-ONYX-02	TBD
MIX-H310D1-A12-HD-T20-ONYX	TBD
MIX-H310D1-A13-HD-T20-ONYX	TBD
MIX-H310D1-A13-HH	MIX-H310D1-A13-HH-FTPM
MIX-H310D1-A10-BSRT	TBD

Note: Include all standard part numbers, R part numbers, and C part numbers.

Yours sincerely,



IPC BU