

1 Products affected

Product hierarchy no. *		Part no.	SBU	Type / Description	Customer part no.		
SBL	PG	PUG	Туре				
80			0000006148	See list below	EMC	FSS-55	

SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected									
5500.2051	5500.2052								


2 Type of change

- Nickel plated steel case instead of aluminium case
- Different shape of external quick connect terminals
- Change of production site

3 Detailed description of change

- Change of product appearance due to new nickel-plated steel case instead of aluminium case
- Different shape of plastic part for external quick connector terminals
- Moved position and turned protective earth terminal to a vertical position
- Change of factory code from SK to SC and origin from SK to CN on product and packaging labels





Product Change Notification						CN FSS-55 case 10 redesign		
owner	creation date	release date	released by	change order no	rev	page	D40 044 500	
segatro	12.03.2020	12.03.2020	canoniar	2018652	В	1 of 2	D10-041-503	





4 Reason of change

- Improved filter performance due to completed closed steel case
- · Reorganization of production process
- · Production site transfer from Slovakia to China

5 Release date

The change will be rolled-out starting wk10/2020 (Date code 2010 or higher on label) and lasts approx. 6 months depending on the variant.

6 Impact of change and recommended action

Form Yes New material and different quick connect terminals

Fit Yes Earth terminal position
Function No No change in function
Manufacturing Yes Change of production site

Label Yes Change on label Packaging No Change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
<u>FSS</u>	

Product Change Notification						PCN FSS-55 case 10 redesign		
owner	creation date	release date	released by	change order no	rev	page	D40 044 502	
segatro	12.03.2020	12.03.2020	canoniar	2018652	В	2 of 2	D10-041-503	