

IA4421 Product Change Notification

Applicable to: Product Part Number: **IA4421**

Prior Product Revision #: **A0**

New Product Revision #: **A1**

	FUNCTION / ISSUE	IMPLEMENTED CHANGES	EFFECTS / CONSEQUENCES
1	Crystal oscillator startup time in default mode.	Circuit modified to improve start-up time	New POR default value of <i>PLL Setting Command</i> = CC77h (bit 4 = '1', changing this control bit to 0 should be avoided).
2	Strong ripple on V_{dd} during POR could cause unpredictable reset behaviour	Improved POR circuit PSRR	none