



**Product information** 

Weller

KHE/P

Code No.: **T0051508099** 

Active Safety Rest with Stop+Go for FE Irons
Second Safety Rest with Fibre Optic Sensor for Extending to 2 Workplaces for FE 75 and FE 80



This safety rest is ESD safe.

Second safety rest with fibre optic sensor for extending to 2 workplaces

The Weller safety rests with Stop+Go function are recommended accessories for FE irons using the WFE or WFE P extraction units.

A fibre optic sensor switches the extraction unit on when theFE iron is removed from the safety rest and when the FE iron is replaced in the safety rest, after a short delay to gather the fumes from any solder on the tip it switches the unit off. This reduces running costs.