



## Product Discontinuance

Document #:PD25233X

Issue Date:22 Feb 2023

<b>Title of Change:</b>	Product Discontinuance for FS35/FS50 products
<b>Last Time Buy Date:</b>	22 Aug 2023
<b>Last Ship Date:</b>	22 Feb 2024
<b>Contact information:</b>	Contact your local onsemi Sales Office or <a href="mailto:Scott.Brow@onsemi.com">Scott.Brow@onsemi.com</a>
<b>Type of notification:</b>	Customers must notify onsemi (< <a href="mailto:PCN.Support@onsemi.com">PCN.Support@onsemi.com</a> >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

### Description and Purpose:

As previously disclosed to all customers, onsemi has sold its wafer FAB in South Portland, Maine. The product produced in this FAB will continue to be foundry business for the new owners, but ultimately all products must exit this FAB. As a result, there are products that are being transferred to an alternative supplier. However, there are products that onsemi will not transfer and therefore will be put on EOL.

onsemi wishes to promptly inform our customer of our intent to exit this portion of our portfolio so that you may plan appropriately and effectively for replacement devices. As we have been given limited time and capacity to support our foundry needs, it is imperative that customers provide lifetime buy orders for the products listed as soon as possible, while replacement devices are designed in.

onsemi has provided a list of replacement devices, where available, to aid in this process.

For those devices that have no recommended replacement identified, onsemi has partnered with Rochester Electronics and Flip Electronics who will carry any remaining device inventory to potentially allow for a continued source after onsemi has completed its business process.

PLEASE NOTE: onsemi may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

#### Americas:

Tom Siegel ([tom.siegel@onsemi.com](mailto:tom.siegel@onsemi.com))  
☎ +1 765 868 5022  
USA

#### Europe:

Andrej Tomasik ([andrej.tomasik@onsemi.com](mailto:andrej.tomasik@onsemi.com))  
☎ +421 33790 2229  
Slovakia

#### Japan:

Isao Usuki ([isao.usuki@onsemi.com](mailto:isao.usuki@onsemi.com))  
☎ +81 3 6880 1771  
Japan

#### Asia Pacific:

Stephen Ng ([stephen.ng@onsemi.com](mailto:stephen.ng@onsemi.com))  
☎ +852 2689 0209  
China

NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, onsemi ALLOWS SIX (6) MONTHS FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

### List of Affected Parts:

**Note:** Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

Device to be Discontinued	Replacement part	Supplier
FAN4800AUM	CM6800	Champion

FAN4800AUN	CM6800	Champion
FAN6204AMX	NCP4306AAHZZADR2G	onsemi
FAN6300AMY	NCP1342AMDCDAD1R2G	onsemi
FAN6300HMY	NCP1342AMDCDAD1R2G	onsemi
FAN6921BMRMY	FL7921RMX	onsemi
FAN6921MLMY	NCP1937C4DR2G	onsemi
FAN9611MX	NCP1632DR2G	onsemi
FL7733AMX	NCL37733BSNT1G	onsemi
FL7734MX	#NONE	#NA
FSFR2100XS	NCP13992ACDR2G	onsemi
FAN73611MX	FAN7382MX	onsemi
FAN7888MX	6EDL04N02PR	Infineon
FAN7388MX	IRS2334	Infineon
FAN73833MX	NCP5304DR2G	onsemi
FAN73832MX	IRS21091S	Infineon
FAN7383MX	IRS21084S	Infineon
FAN7390MX	NCP5183DR2G	onsemi
FAN73901MX	NCP5181DR2G	onsemi
FAN7385MX	IRS25752L	Infineon
FAN7362MX	IRS2117S	Infineon
FAN7391MX	IR21814	Infineon
FSL117MRIN	#NONE	#NA
FSL4110LRN	#NONE	#NA
FSL4110LRLX	#NONE	#NA
FAN3100TMPX	MIC44	Microchip
FAN3100TSX	MIC44	Microchip
FAN3226TMPX	MIC4426	Microchip
FAN3226TMX	MIC4426	Microchip
FAN3224CMPX	UCC27524	Texas Instruments
FAN3224TMNTXG	UCC27524	Texas Instruments
FAN3224TMPX	UCC27524	Texas Instruments
FAN3224TMX	UCC27524	Texas Instruments
FAN73912AMX	IR2213	Infineon
FAN73912MX	IR2213	Infineon
FAN73711MX	IRS21850	Infineon
FAN7392MX	IRS2113S	Infineon
FAN73933MX	IRS21834S	Infineon