

167 Technology Dr.

Irvine | CA 92618 | USA

Tel: 949-453-3990 Fax: 949-453-3995 www.lantronix.com

Date: 02/01/2012 **PCN No.:** 199

PRODUCT CHANGE NOTICE

Dear Valued Lantronix Customer,

Lantronix is pleased to announce the release of new and improved Micro125 firmware version 6.8.0.4 and Web Manager Version 1.9.0.3.

The easy upgrade to firmware version 6.8.0.4, will be available at the Lantronix website, upgrades the product to the most up to date version of software.

Part Numbers	Product Description	Current Revision	New Revision with Firmware 6.8.04 and 1.9.03
MO00AA003-01R	Micro125, No RJ45 connector, No LEDS, with TTL pin header, RoHS	A11	B11
MO00AA0E3-01R	AES Encrypted Micro125, No RJ45 connector, No LEDS, with TTL pin header, RoHS	A11	B11
MO11AA003-01R	Micro125 with RJ45 connector, LEDS, with TTL pin header, RoHS	A11	B11
MO11AA0E3-01R	AES Encrypted Micro125 with RJ45 connector, LEDS, with TTL pin header, RoHS	A11	B11
MO22AA003-01R	Micro125, Pin header for Ethernet, Pin header for LED connection, with TTL pin header, RoHS	A11	B11

SCHEDULE: Please note that factory shipments with new Micro125 version 6.8.0.4 and Web Manager 1.9.0.3 will approximately begin shipping on **August 15th**, **2013**.

For customers that would like to take advantage of the new capabilities immediately, the new firmware and associated release notes will be available for download from our website on **February 15th**, **2013**. http://www.lantronix.com/support/downloads.html

If you have any questions, please contact your sales representative or Lantronix Customer Support at (866) 649-0721 or (949) 453-3990 x342.

