

www.aaeon.com

## **Product Change Notice**

QD4-099 Rev.A1

Product(s) Affected: EMB-H110B series

Effective date: May 10, 2024

Last time buy date: October 31, 2024

P	roduct	Change	Description:
F 1	Oddol	Change	Description.

- Audio codec EUA2012AJIR1 was EOL and recommend EUA2075AJIR1 which is not pin-to-pin with current one. Thus, AAEON needs to re-spin a new version PCB with new audio schematic design, BIOS and driver do not need to change for the modification.
- Duo to the LAN jack mold was broken, vendor UDE change to a new mold and then keep manufacturing. The ASUS EOL PN is 12014-00163200/ 12014-00351700 (Vendor PN: 24-00019NN43-1[Housing Color: Black; Location: LAN2/LAN1]). New ASUS LAN jack PN is 12014-00357000 (Vendor PN: S22-AU-0025 Housing Color: Black). Both connectors are same dimension (length, width and height=21.5\*15.75\*13.80mm). Location: LAN1, LAN2.

For the new part number, please refer to below comparison table, please be kindly noted and thanks for your attention and understanding.

R۵	nefits:□	∃ In	nn:	act	S.	
	11631113			CA ( ) [ .	-7-	33 A 25 W S

To avoid material EOL issue and keep product production on the same PCB.

## **Details of Affected Products:**

IPC BU

Pre-Change	Post-Change	
EMB-H110B-A14-HH-K	EMB-H110B-A15-HH-K	
EMB-H110B-A10-HH-K	EMB-H110B-A15-HH-K	

Note: Include all standard part numbers, R part numbers, and C part numbers.

Yours sincerely,

AAEON Technology Inc. 5F, No.135, Lane 235, Pao Chiao Rd. Hsin-Tien Dist., New Taipei City 231, Taiwan, R.O.C.

TEL: +886-2-8919-1234 FAX: +886-2-8919-1056