

Computing Platform Service Partner

www.aaeon.com

Product Change Notice

QD4-099 Rev.A0

Product(s) Affected:

ACP-1106HTT-A1-1011 ACP-1106HTT-A3-1011 ACP-1106HTT-B1-1011 ACP-1106HTT-B3-1011

Date Effective: 2019.12.24

Due to the original Touch of ACP-1106 already phase out, we decide to adopt a new generation Touch with same spec to replace the original one. This replacement Touch pass functions test without effect system performance or drivers change. For the new part number, please refer to below comparison table, please be kindly noted and thanks for your attention and understanding.

Date of Publication: 2019/12/24

Changes to Product:

Purpose of Change:

Due to original Touch of ACP-1106 already phase out, we will replace it by next generation qualified components. All functions pass test without effect system performance or drivers.

AAEON Technology Inc. 5F, No.135, Lane 235, Pao Chiao Rd., Hsin-Tien Dist., New Taipei City 231, Taiwan, R.O.C. TEL: +886-2-8919-1234 FAX: +886-2-8919-1056



www.aaeon.com

Benefits Impacts:

Model :

ACP-1106HTT-A1-1011 ACP-1106HTT-A3-1011 ACP-1106HTT-B1-1011 ACP-1106HTT-B3-1011

Driver:

Keep the same

BIOS:

Keep the same

OS Support:

Keep the same

Pre-Change		Post-Change	
ACP-1106HTT-A1-1011		ACP-1106HTT-A1-1012	
ACP-1106HTT-A3-1011		ACP-1106HTT-A3-1012	
ACP-1106HTT-B1-1011		ACP-1106HTT-B1-1012	
ACP-1106HTT-B3-1011		ACP-1106HTT-B3-1012	
Issue Date	2019.12.24	Issue by	Ethan Chiu

AAEON Technology Inc. 5F, No.135, Lane 235, Pao Chiao Rd., Hsin-Tien Dist., New Taipei City 231, Taiwan, R.O.C. TEL: +886-2-8919-1234 FAX: +886-2-8919-1056